



THE QUALITY CHICKEN PEOPLE

ALLEN FAMILY FOODS, INC.

P.O. BOX 63

HARBESON, DE 19951

302/684-1640 FAX: 302/684-1638

October 10, 2000

Mr. Allen McCloskey
Delaware Department of Natural Resources
and Environmental Control
Division of Water Resources
89 Kings Highway
Dover, Delaware 19903

SUBJECT: ANOXIC REACTOR B

Dear Allen:

This letter is to follow up on the repair of the liner in the anoxic reactor. On September 15, we noticed that the air supply lines had been moved over approximately six feet. We bypassed the pond and pumped it out on September 16, we could then see that the liner had a small tear by the mixer pad, creating a bubble between the two layers. This was caused by the liner separating from the anchors that hold the air lines around the concrete pad for the floating mixer. We contacted Land Saver who installed the liner and they came in on October 2, 2000. They removed the anchors around the concrete pad and shortened the two air lines so nothing is penetrating through the liner. The liner was patched and inspected for any other damage. We were back on line that same day with no problems.

Should you have any further questions please call at 302 684-1640.

Sincerely,

Thomas Brinson
Environmental Manager

mtb

cc: Buck Kornemann, Plant Manager
Larry Enders, Director of Technical Services