

Greenville Overlook Environmental Daily Status Report



Date: 10/15/09

Weather: Rain **Temperature:** 50s° **Winds:** 0-3 mph (East-Southeast)

Items Completed Today BrightFields was on site from 0704 to 1133 to monitor perimeter airborne dust levels, construction activities, and remediation activities. Due to rain, perimeter dust meters were not set up and work was halted at 1133.

BrightFields collected soil samples from Green 5 (Remediation Area B5). Soil samples were analyzed onsite utilizing an X-Ray Fluorescence analyzer. Selected samples were sent to the laboratory for confirmation analysis.

Items Ongoing:

Lewis Environmental will continue blending Fairway 8 and Fairway 9. BrightFields will continue to monitor remedial activities and collect soil samples for analysis.

Material Management (Soil/Wood/Water): None

Personal Protection Equipment Used by Workers:

Used: Safety glasses Hard hat Steel toe boots
 Nitrile gloves Hearing protection Other:

Sampling or Monitoring Completed:

(if yes, please specify the reason.)

Air monitoring on site No Yes, reason: Rain

Soil sampling on site No Yes, reason: screening and confirmatory samples used to assess contaminant concentrations in the soil.

Visitors Briefed on Environmental Conditions: None

Completed By: John Stratton and John Stevens

