

Greenville Overlook Environmental Daily Status Report



Date: 10/28/09

Weather: Rain **Temperature:** 60s° **Winds:** 0-3 mph (East)

Items Completed Today BrightFields was on site from 0718 to 1240 to monitor perimeter airborne dust levels, construction activities and remediation activities. Perimeter dust meters were not set up due to rain.

BrightFields monitored remediation activities at areas A3 and B5.

Items Ongoing:

Lewis Environmental will continue blending and BrightFields will continue to monitor remedial activities and collect soil samples for analysis.

Material Management (Soil/Wood/Water): None

Personal Protection Equipment Used by Workers:

Used: Safety glasses Hard hat Steel toe boots
 Nitrile gloves Hearing protection Other:

Sampling or Monitoring Completed:

(if yes, please specify the reason.)

Air monitoring on site No Yes, reason: Rain

Soil sampling on site No Yes, reason: no samples collected today.

Visitors Briefed on Environmental Conditions: None

Completed By: John Stratton

Time	Location	Dust (mg/m ³)	Notes (i.e.: source of problem, weather, etc.)	Actions Taken

Action Levels for Dust (sustained, exceeding 5 minutes):	
<u>Dust Level</u>	<u>Level of Protection</u>
0.8mg/m ³	Level D plus engineering controls such as wetting surface.
≥ 2 mg/m ³	Stop work, evacuate workers and implement more stringent engineering controls and possible Level C.