

Community Hazard/Flooding Photos

Inland Community Flooding

Milford

Milton

Stanton

Seaford

Dover

Glennville

Wilmington and Western Railroad



Community Hazard/Flooding Photos – Inland Community Flooding



Milton, Delaware (Sussex County)

Northeaster – March 6-8, 1962

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

Milford, Delaware
Northeaster – May 12, 2008

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

Milford, Delaware
Northeaster – May 12, 2008

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

Stanton, Delaware

Tropical Storm Henri – September 2003

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

Seaford, Delaware

June, 2006

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

Seaford, Delaware

June, 2006

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

Dover, Delaware

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware Geological Survey

Glenville Park (New Castle County), Delaware
Adjacent to Red Clay Creek

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware Geological Survey

Glenville Park (New Castle County), Delaware
Adjacent to Red Clay Creek

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

New Castle County, Delaware
Tropical Storm Henri – September 2003

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

New Castle County, Delaware

Tropical Storm Henri – September 2003

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

Route 4, near Stanton, Delaware
Tropical Storm Isabel – September 2003

Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

Route 4, near Stanton, Delaware
Tropical Storm – September 2003


Community Hazard/Flooding Photos – Inland Community Flooding



Photo courtesy Delaware DNREC

Marshallton vicinity, Red Clay Creek, New Castle County, Delaware
Tropical Storm Isabel – September 2003

Community Hazard/Flooding Photos – Inland Community Flooding



Wilmington, Delaware

Depiction of flooding that would occur at a flood elevation of 12 feet above sea level. This flood level was actually recorded in Wilmington during the storm of 1878.