



State of Delaware Public Record Summary Information on Underground Storage Tanks (UST)

Public Record Posted Date: December 23, 2008

General Information:

Total Number of UST Facilities subject to federal regulations: 509

Total Number of USTs: 1420

Summary Information for On-Site Inspections:

Number of UST Facilities Inspected (10/1/07through 9/30/08): 156

Percent of facilities found to be in significant operational compliance: 79%

Note: Tank, facility, and on-site inspection information is based on definitions and compliance requirements found in the DE Admin Code 1351, State of Delaware *Regulations Governing Underground Storage Tank Systems*;

Summary Information for Release Sources and Causes:

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	26	32	2	8	1	4	0	0	2	8	0	0	0	0	21	81
Piping	5	6	0	0	0	0	2	40	0	0	0	0	0	0	3	60
Dispenser	17	20	1	6	0	0	0	0	0	0	0	0	0	0	16	94
Turbine Pump (STP)	2	3	0	0	0	0	0	0	0	0	0	0	1	50	1	50
Delivery Problem	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Known but not listed above.	2	3	0	0	0	0	1	50	0	0	0	0	0	0	1	50
Unknown	30	36													30	100
Totals	82	100%	3	4%	1	1%	3	4%	2	2%	0	0%	1	1%	72	87%

Note: Release, source and cause information is based on data collected by State of Delaware employees and are identified through field observation and confirmed with soil testing when retrofit, repair, tank removal, or hydrogeological investigation activities are conducted.

To obtain facility specific information please use our environmental navigator system found at: <http://www.nav.dnrec.delaware.gov/dnreceis/> or call Mr. Alex Rittberg at 302-395-2500.