



State of Delaware Public Record Summary Information on Underground Storage Tanks (UST)

Public Record Posted Date: December 31, 2018

General Information as of 9/15/18:

Total Number of UST Facilities subject to federal requirements: 415

Total Number of USTs: 1138 subject to federal requirements

Summary Information for On-Site Inspections:

Number of UST Facilities Inspected (9/15/17 through 9/15/18): 134

Percent of facilities found to be in significant operational compliance: 96%

Note: Tank, facility, and on-site inspection information is based on definitions and compliance requirements found in the DE Admin Code 1351, State of Delaware *Regulations Governing Underground Storage Tank Systems*;

Summary of Release Sources and Causes for the time period 9/15/17 through 9/15/18:

Number of Confirmed Releases during the time period 9/15/17 through 9/15/18: 45

Source (% is based on the total number of releases with known sources)			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	14	47	0	0	2	14	1	25	5	36	0	0	0	0	7	50
Piping	2	7	0	0	0	0	0	0	2	100	0	0	0	0	0	0
Dispenser	4	13	0	0	0	0	0	0	0	0	0	0	0	0	3	75
Turbine Pump (STP)	1	3	0	0	0	0	0	0	0	0	0	0	0	0	1	100
Delivery Problem	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Other	9	30	0	0	0	0	1	11	0	0	0	0	3	33	6	67
Unknown	15															
Total number of releases with known sources (% of known)	30	100	0	0	2	7%	1	3%	7	23%	0	0%	3	10%	17	57%

Note: Release, source and cause information is based on data collected by State of Delaware employees and are identified through field observation and confirmed with soil testing when retrofit, repair, tank removal, or hydrogeological investigation activities are conducted. To obtain facility specific information please use our environmental navigator system found at: <http://www.nav.dnrec.delaware.gov/DEN3/> or call Mr. Alex Rittberg at 302-395-2500.