



# NPDES Recon Inspection Division of Water Surface Water Discharges Section

Delaware Department of Natural Resources and Environmental Control  
89 Kings Highway, Dover, DE 19901  
Tel (302) 739-9946, Fax (302) 739-8369

Inspector(s) **Nicole Smith** Date **2/2/2012** Time In **10:05:00 AM** Time Out **11:05:00 AM**  
Inspection Status **Compliant**

### Facility Information

Name **Pinnacle Foods** Permit # **DE0000736**  
Location **29984 Pinnacle Way, Millsboro, DE 19966**  
Contact **Randy Spence** Phone # **(302) 934-3833**

### Comments

Nicole Smith and Chris Cleaver arrived on site at approximately 1005 hrs.  
Met with Robert Lynch (DRC Operator).  
Toured facility beginning with headworks, flow EQ, step feed, aeration and clarifiers, UV disinfection and outfall 001, digesters and sludge lagoon.  
Effluent from outfall 001, clear with slight green tint, no sheen, no odor, no floating solids, no turbidity.  
Checked all storm water outfalls - while observing storm water outfall 004, turbid, dark gray in color, poor quality water in collection pit (no discharge at time of inspection), potential overflow during storm event. At time of observation, water was being pumped to wastewater treatment plant. Asked them to look at options for handling situation in the future.  
All other storm water outfalls ok at time of inspection.  
Short closing meeting with Robert Lynch.  
Departed facility at approximately 1105 hrs.

### Inspector Certification

Print Name and Title Nicole Smith Sr. Env. Comp. Spec. Chris Cleaver Env. Comp. Spec.  
Signature and Date Nicole Smith 2/1/12 Chris Cleaver 2/1/12