



State of Delaware Public Record Summary Information on Underground Storage Tanks (UST)

Public Record Posted Date: January 19, 2011

General Information:

Total Number of UST Facilities subject to federal regulations: 478

Total Number of USTs: 1331

Summary Information for On-Site Inspections:

Number of UST Facilities Inspected (10/1/09 through 9/30/10): 187

Percent of facilities found to be in significant operational compliance: 61%

Note: Tank, facility, and on-site inspection information is based on definitions and compliance requirements found in the DE Admin Code 1351, State of Delaware *Regulations Governing Underground Storage Tank Systems*;

Summary of Release Sources and Causes for the time period 10/1/09 through 9/30/10:

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%	
Tank	12	26	1	8	1	8	0	0	1	8	0	0	0	0	9	75
Piping	5	11	0	0	0	0	1	80	0	0	0	0	0	0	3	60
Dispenser	17	36	0	0	0	0	1	6	0	0	1	6	1	20	15	88
Turbine Pump (STP)	1	2	0	0	0	0	1	100	0	0	0	0	0	0	0	0
Delivery Problem	2	4	1	50	1	50	0	0	0	0	0	0	0	0	0	0
Other	10	21					1	10							9	75
Totals	47	100%	2	4%	2	4%	4	9%	1	2%	1	2%	1	2%	36	77%

*** Please note there were 28 additional releases with unknown sources during the reporting period.**

Note: Release, source and cause information is based on data collected by State of Delaware employees and are identified through field observation and confirmed with soil testing when retrofit, repair, tank removal, or hydrogeological investigation activities are conducted.

To obtain facility specific information please use our environmental navigator system found at: <http://www.nav.dnrec.delaware.gov/dnreceis/> or call Mr. Alex Rittberg at 302-395-2500.